Handheld vibration meter





SPECIFICATIONS

O :		7.05 0.00 41 (00.0.0.0.0.)
Size		7.95x2.36x1" (20x6x2.6 cm)
Weight (excluding magne	t)	280 grams (9.8 oz)
Environmental: Water Operating temperatur Storage temperature	e	IP67 waterproof 0° to +50°C –20° to +70°C
Power supply		2x AA batteries
Battery life		50 hours normal use
Frequency ranges:	ISO BDU	2 Hz - 1 kHz 1 Hz - 15 kHz
Max frequency resolution		1.25 Hz at 800 lines FFT setting
Displayed amplitude units Acceleration Bearing damage Velocity	: :	g BDU in/sec or mm/sec
Displayed frequency units	3	Hz or CPM
Input range		±50 g
Dynamic range, 0.01 g res	olution	72 dB
VA bands		Auto set-up
Accelerometer connection	า	internal sensor
Display		OLED full color, high contrast
Selectable languages		English (default), Spanish, Portuguese, French, Italian, Turkish, Chinese, Japanese and Korean

Accessories supplied: MAC002 protective boot with magnets; MAC003 carrying case with insert; extended stinger



Key features

- Versatile meter for walkaround monitoring programs
- Built-in ISO alarms
- 100 and 800 line FFT spectrum
- · BDU reading
- High performance accelerometer with stinger
- · Manufactured in ISO 9001 facility



Note: Due to continuous process improvement, specifications are subject to change without notice. This document is cleared for public release.

MachineryMate[™] vibration meter kits



MAC800 series

Wilcoxon's handheld MAC800 vibration meter analyzes and displays vibration signals, helping users identify machine faults before they impact operation or lead to failure. The meter comes with built-in band filters for unbalance, misalignment and looseness, and its low Hz range allows readings on machinery running at speeds as slow as 120 RPM.

When used with the included DataMate software, the MAC800 kit can become the foundation of a plantwide condition monitoring program, supporting up to ten machines. Upgrading to DataMate PRO allows monitoring of up to 1,000 machines. Other options for extended capabilities include Bluetooth headphones for auditory monitoring and a strobelight attachment for run speed analysis.

MachineryMate kits		kits	Accessories included
MAC800	MAC810	MAC820	Accessories included
✓	✓	✓	MAC800 meter and Datamate software
✓	✓	✓	USB docking cradle
✓	✓	✓	Protective boot
✓	✓	✓	100 mV/g sensor with magnet
✓	✓	✓	Carrying case
	✓	✓	Strobelight attachment (MAC004)
	✓	✓	DataMate PRO software (MAC005)
		✓	Bluetooth headphones (MAC006)
		✓	Headphones case (MAC007)

Dogo mental de la constante de

Key features

- · Data trending software
- Internal data storage
- Built-in ISO alarms and Bluetooth capability
- Standard cable mounted accelerometer with magnet
- BDU reading to easily identify bearing problems
- 800 line FFT spectrum
- Manufactured in an approved ISO 9001 facility

Certifications



Note: Due to continuous process improvement, specifications are subject to change without notice. This document is cleared for public release.

MachineryMate[™] vibration meter kits



MAC800 series

SPECIFICATIONS

METER	
Size	7.95 x 2.36 x 1 in. (20 x 6 x 2.6 cm)
Frequency ranges: ISO Low speed ISO BDU	10 Hz - 1 kHz (600 - 60,000 CPM) 2 Hz - 1 kHz (120 - 60,000 CPM) 1 Hz - 10 kHz (60 - 600,000 CPM)
Max frequency resolution	75 CPM at 800 lines FFT setting
Displayed amplitude units	Acceleration: g Bearing damage: BDU Velocity: in/sec and mm/sec Displacement: mils and mm
Displayed frequency units	CPM or RPM
Input range	±60 g
Dynamic range, 0.01 g resolution	96 dB
VA bands	Auto set-up
Display	OLED full color, high contrast
Selectable languages	English (default), Spanish, Portuguese, French, Italian, German
Weight (excluding magnet)	9.8 oz (280 grams)
Environmental: Water Operating temperature Storage temperature	IP67 waterproof 0° to +50°C -20° to +70°C
Power supply	2x AA batteries
Battery life	20 hours normal use
SENSOR	
Sensor	780FM-2-J88C integral cable accelerometer
Sensitivity	100 mV/g
Sensitivity tolerance	±15%
Acceleration range	80 g
Frequency range, ±3 dB	0.4 Hz to 12 kHz
Acceleration limit	500 g
Cable	6 ft. coiled cable
Magnet	Two-pole 40 lbf, detachable

Accessories supplied:

- 780FM-2-J88C accelerometer with integral cable
- DataMate software
- MAC001 docking station with USB cable
- MAC002 protective boot with magnets
- MAC003 carrying case with insert

Accessories available:

- MAC004 strobelight attachment
- MAC005 DataMate PRO software
- · MAC006 Bluetooth headphones
- MAC007 headphones carrying case

Note: Due to continuous process improvement, specifications are subject to change without notice. This document is cleared for public release.